

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950

AIRPORT LIGHTING CO 108 FAIRGROUNDS DR MANLIUS, NY 13104 **REVISION DATE: February 18, 2022**

ORIGINAL ISSUE DATE: October 5, 2021

Recertification due: November 2028

An Activity Sponsored and Administered by Intertek

AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacements parts or non-production components.

| L-881(L) –Abbreviated Precision Approach Path Indicator (AC 150/5345-28H) | | | |
|--|---------|-------------------------------|--|
| Style | Class | Manufacturer's Catalog Number | |
| А | Ш | 88-1AX0X0 (958) | |
| В | II | 88-1BX0X0 (958) | |
| | Style A | Style Class A II | |

NOTE: (958) 88-00200 RED and WHITE LED

Equipment meets the requirements of FAA Engineering Brief No. 67D additional requirements for "Light Sources Other Than Incandescent and Xenon for Airport and Obstruction Lighting Fixtures" dated March 6, 2012.

- 1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
- 2. Product tested and Report issued by: Airport Lighting Co., Intertek

(A) Report No:104383028CRT-001 Rev 2; 104383028BOX-001; ALC-210407-1; ALC-210407-3

NOTE: PLEASE REVIEW, AND ADVISE

IF DATA, AS SHOWN, NEED TO BE

ADMINISTRATOR AT INTERTEK IMMEDIATELY

(B) Date of Report: 2/2022; 02/2021; 04/2021; 04/2021; 04/2021

Approved for Certification by:

Jeremy N. Downs, PE, Program Administrator Date: February 18, 2022

CORRECTED.